

Revisions to this document are noted
by a stripe in the left-hand margin

SIL 55-TR-80, Rev. C
May, 2005
Page 1 of 1

SUBJECT: Towing of Vehicles Equipped with Allison Transmissions

MODELS AFFECTED: All Allison Commercial Transmissions Except for 3070PT and 3700SP

When towing or pushing any vehicle equipped with an Allison transmission listed above, the transmission's outputs must be disconnected regardless of distance or speed traveled.

KS / SL4134EN

4695597

Copyright © 2005 Allison Transmission, Inc. All Rights Reserved.

***Please Note:** Allison Transmission Service Information Letters are intended for use by professional, trained technicians, not for the "do-it-yourselfer." They are written to inform those technicians of conditions that may occur on some transmission models (or serial numbers ranges) or to provide information that could assist in the proper servicing of a specific Allison transmission. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, do not assume that the Service Information Letter applies to your transmission, or that your transmission has the condition described. Product evolution and information updates are inevitable. Please see your authorized Allison Transmission service dealer or distributor to understand if your particular transmission may benefit from the information contained within the Service Information Letter.*